

Bristol - Isolocork on Lime Render

Spray Cork Project Case Study

Project overview

External renovation of an existing lime-rendered residential property in Bristol. Isolocork spray cork was applied as the external finish, retaining a textured appearance while providing a continuous cork-based coating across the treated elevations.



Existing condition

Weathered lime-rendered wall before preparation, with visible staining and cracking.



Substrate preparation

Existing finish prepared and local defects addressed before the Isolocork application.



Application in progress

Openings and adjoining surfaces protected while the external coating work progressed.



Coating application

Isolocork applied across the rear elevation to form a continuous textured finish.

Completed Finish

Bristol - Isolocork on Lime Render



Finished surface

Close view of the completed Isolocork finish around the upper rear elevation.



Completed elevation

Overall view of the completed rear elevation following application.

Project summary

This project shows Isolocork used as part of the renovation of an existing rendered property. The system was applied over the prepared external substrate and used to create a continuous cork-based finish across the treated walls.

Location

Bristol, UK

Application

External wall renovation

Existing substrate

Lime-rendered façade

System

Isolocork spray cork

[Watch the Bristol project video ->](#)

Isolocork Spray Cork | CorkEco Solutions