

Manchester - Isolocork Interior Application

Spray Cork Project Case Study

Project overview

Interior renovation of an existing residential property in Manchester. Isolocork spray cork was applied to internal wall surfaces to create a continuous textured cork-based finish while working around retained architectural features.



Interior preparation

Room prepared for renovation before the Isolocork finish was applied.



Surface texture

Close view showing the texture of the applied Isolocork finish.



Interior application

Isolocork applied to the internal walls around the fireplace and retained decorative cornice. surfaces.



Continuous finish

Continuous cork-based finish applied across the treated internal wall

Completed Finish

Manchester - Isolocork Interior Application



Finished texture

Detailed view of the completed textured Isolocork surface.



Completed interior

Room view showing the Isolocork finish across the renovated interior.

Project summary

This project shows Isolocork used as an internal wall finish during the renovation of an existing Manchester property. The walls and adjoining features were protected and prepared before the spray cork was applied, creating a continuous textured finish across the treated surfaces.

Location

Manchester, UK

Application

Interior wall renovation

Existing substrate

Existing internal wall finish

System

Isolocork spray cork

[Watch the Manchester project video ->](#)

Isolocork Spray Cork | CorkEco Solutions